

Date/Time	Incident Address	Incident Type	Apparatus List	Narrative
2/6/2024 4:07	4000 block North WOODSIDE	1111 - Single story House fire	BC331, BC380, CC001, EN008, EN330, EN331, EN332, PM331, RE008, SO331, TN332, AP379, FI331, FI381, PM008, SR332	<p>BC331 responded without incident to a reported house fire. EN331 arrived and reported working fire conditions, were stretching an attack line and established Command in the offensive strategy. I performed a command transfer with EN331 and assumed Command. We remained in the offensive strategy.</p> <p>PM331 was originally assigned medical but was later reassigned to perform rehab along with PM008. There was heavy smoke coming from the garage on the A side of the house with some smoke coming from the eaves along the length of the house. EN331 was making access to the garage to begin fire attack.</p> <p>EN008 was initially assigned to establish a water supply to EN331 but were unable because of blocked access. They were reassigned to stretch a 2nd handline from EN331 to the interior to perform a primary search and check for fire extension.</p> <p>EN332 was assigned to establish a water supply to EN331. Once complete, EN332 was assigned on-deck.</p> <p>SO331 was assigned safety and to perform a 360. He reported turbulent smoke from the gable vent on the C-side and believed the fire had extended to the attic.</p> <p>EN331 extinguished the fire in the garage and proceeded to the interior of the house and met EN008. EN008 declared a primary all clear and EN331 called the fire under control. EN331 exited for rehab and were replaced with EN332. EN330 assigned to replace EN332 on deck. EN008 exited to rehab and EN332 replaced them interior. EN332 and EN330 worked to overhaul the fire and loss stopped was achieved.</p>

2/7/2024 10:23	5000 block North CAMINO DE OESTE	1111 - Single story House fire	BC331, BN001, CC001, EN330, EN331, EN332, EN335, PM331, SO331, TN332, AP341, FI331, FI381, PM334, SR333, DV331	<p>Full Alarm units responded Code 3 for reported Structure 1 assignment. Upon arrival, EN332 provided an initial report of a small single-story home with working fire conditions in the garage. EN332 assumed command and operated in the offensive strategy. EN332 pulled an attack line and cut the garage door for access. EN322 attacked the garage fire and completed a primary search.</p> <p>Command transfer was completed from EN332 to BC331 and remained in an offensive strategy. SO331 arrived and was assigned 360, utilities and safety. EN331 arrived on scene and was assigned to complete a water supply from hydrant to EN332. DC331 arrived and was assigned to occupant services. EN330 arrived on the scene and was assigned to take a second attack line, complete a primary search of the structure, and check for extension into the dwelling from the garage. EN331 completed the assignment and was assigned on deck, Alpha side with RIC responsibilities.</p> <p>PM331 and PM334 were assigned to medical and rehab. EN332 reported the fire under control with PAR. EN332 checked for extension into the attic with negative extension. EN330 reported a negative fire extension, and all cleared from inside the structure.</p> <p>SO331 completed air monitoring of the structure and readings were within acceptable limits.</p> <p>EN335 and TN332 were cleared the scene from Level 1 staging. SR333 arrived on the scene and was assigned to occupant services. Fire investigation responded, and the scene was turned over for investigation.</p> <p>Command terminated and units returned to service.</p>
----------------	-------------------------------------	-----------------------------------	---	---

2/13/2024 15:29	3000 block West ARROWWOOD	1111 - Single story House fire	BC331, BC332, EN333, EN338, EN342, EN379, EN381, PM333, SO331, AP379, FI331, FI381, PM381, SR332	House fire. EN338 arrived, gave size up, assumed command. One-story house, with light smoke from eaves on A side. Secured water supply, pulled 1.75" line through A for search/rescue/fire control. Assigned EN333 to assist with securing hydrant supply. Assigned EN342 to pull additional line through garage for search/rescue/fire control. BC332 copied all assignments, assumed command. Assigned EN379 to on-deck. Assigned SO331 to safety/utilities. Assigned PM333 to medical, AP379 to rehab, and PM379 to medical with rehab. Assigned EN333 to bring fognail to A side for potential attic involvement. EN338 reported fire under control , no extension, low heat, light smoke. EN338 asked EN333 to discontinue fognail attack. EN342 reported primary all clear, coming out for recycle, EN379 assigned to replace EN342 interior. SO331, EN342, and PM379 cleared from call to respond to another fire and provide assistance. EN338 stated loss stopped, overhauling area. EN379 reported secondary search clear. FI331 and FI381 on scene for investigation. SR331 on scene for homeowner assistance. All crews placed into service, scene turned over to investigators. Command terminated, cleared scene.
-----------------	------------------------------	-----------------------------------	---	---

2/2/2024 8:58	2000 block West WETMORE	1113 - Multi-story or commercial or unsprinklered Building	BC332, BN001, CC001, EC001, EN020, EN331, EN332, EN333, LD004, PM008, RE008, TN332, SO331, SQ338, FI331	<p>EN331 code 3 response with other units for reported Structure 2 fire.</p> <p>UA EN331 first on scene of very large 2 story commercial with nothing showing. EN331 assumed Wetmore command and began investigation. RP met EN331 on delta side and reporting machinery fire that has been extinguished by onsite personnel using dry chem extinguisher. Upon investigation EN331 confirmed RP's report, found negative fire problem and cancelled balance except for EN332. EN331 and EN332 performed ventilation of building using PPV fans and building's owns exhaust system and fans.</p> <p>RP states fire originated at and stayed confined to printing press #2, due to an unknown malfunction of the machine. RP was at his desk working when he noted the normal drone of the machine operating stopped, he went to investigate and the machine operator confirmed there was a fire and proceeded to use a dry chem extinguisher to put it out.</p> <p>EN331 used TIC to confirm there was no more heat no potential for rekindle.</p> <p>FI331 arrived on scene to begin investigation. After building was fully ventilated, command was terminated and NWFD units returned to service.</p>
---------------	-------------------------	--	---	---

2/23/2024 18:27	2000 block West CURTIS	121 - Fire in mobile home	BC331, BC380, EN330, EN331, EN332, EN333, PM331, RE008, SO331, TN332, AP379, FI331, FI381, PM330, SR331	<p>BC331 responded code 3 with full alarm for house fire. Upon arrival BC331 staged in front of dispatched address and initiated command transfer with EN331. EN331 reporting working fire conditions, from A/B side. EN331 secured a water supply and pulled attack line for primary search and fire control.</p> <p>PM331 staged and assisted with water supply.</p> <p>EN332 staged and assigned to pull a second line to the interior for primary search and fire control. EN332 forced entry on Alpha side.</p> <p>BC331 assumed command in the offensive strategy.</p> <p>Rescue 8 arrived assigned to assist pump 331 on Alpha side.</p> <p>EN330 staged and assigned on-deck</p> <p>EN333 Staged Level 1.</p> <p>SO331 performed 360, secured utilities and assumed safety. No exposures.</p> <p>EN331 CAN report of low visibility, moderate heat, no needs.</p> <p>EN332 CAN report with primary all clear, requesting ventilation.</p> <p>EN331 confirme all clear and fire control. Pump 331 assigned to place fan at front door.</p> <p>EN331 status change, low on air ready for recycle, requesting a crew to replace them for overhaul.</p> <p>EN330 assigned face to face wth EN331 for secondary and overhaul.</p> <p>EN333 assigned to on-deck.</p> <p>EN332 status changed ready to recycle, no need to replace.</p> <p>EN332 assigned rehab.</p> <p>Rescue 8, Tender 332, PM330 released.</p> <p>EN331 recycle completed. Scene was turned over for fire investigation and units cleared.</p>
-----------------	---------------------------	------------------------------	---	--